

Type	L #	Hits	Search Text	DBs	Time Stamp	Com ment S	Error Definition	Erro rs
1	BRS	L1 284	method and (manufactur\$4 or produc\$4) and (cam or camshaft) and (expansion with (hydro\$5 or hydrau\$3))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/12/16 10:54			0
2	BRS	L2 424	method and (manufactur\$4 or produc\$4) and (cam or camshaft) and ((expansion or expanding or expand) with (hydro\$5 or hydrau\$3))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/12/16 10:55			0
3	BRS	L3 41	2 and (axial near3 (force or load))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/12/16 10:56			0